


STEAMIST®

3 Phase Wiring Diagram

Models: TSG-7 thru TSG-15



Specification Chart

Model No.	Max. Cu. Ft. For Area Up To	KW	Volt	Phase	Amps	Line Fuse
TSG-7	250	7.5	240 208	3 3	18 21	30 30
TSG-10	475	10	240 208	3 3	24 28	30 40
TSG-12	550	12	240 208	3 3	29 33	40 40
TSG-15	675	15	240 208	3 3	36 42	50 50

90°C copper wire is required for generator connection. Installation shall be in accordance with NEC and local electrical codes.